

Influence of manmade effects on geomorphology, bathymetry and coastal dynamics in a monsoon affected river outlet in Southwest coast of Sri Lanka

G.P. Gunasinghe^{1,2,*}, Lilani Ruhunage³, N.P. Ratnayake¹, A.S. Ratnayake⁴, G.V.I. Samaradivakara¹, Ravindra Jayaratne⁵

¹Department of Earth Resources Engineering, Faculty of Engineering, University of Moratuwa, Moratuwa, Sri Lanka.

²Department of Spatial Sciences, KDU Southern Campus, Nugegalayaya, Sewanagala, Sri Lanka (Present Address).

³Coast Conservation and Coastal Resource Management Department, Maligawatte, Colombo, Sri Lanka.

⁴Department of Applied Earth Sciences, Faculty of Applied Sciences, Uva Wellassa University, Passara Road, Badulla, Sri Lanka.

⁵School of Architecture, Computing and Engineering, University of East London, Docklands Campus, 4-6 University Way, London E16 2RD, UK.

* Corresponding Author:

E-mail Address: prasadh@kdu.ac.lk (G.P. Gunasinghe)

Postal Address: Department of Spatial Sciences, KDU Southern Campus, Nugegalayaya, Sewanagala, Sri Lanka (Present Address).




Fig. 1



(b)




Fig. 2




Fig. 3




Fig. 4




Fig. 5







Fig. 6







Fig. 7







Fig. 8